25X1

25X1

25NOV 1964

SUBJECT: Naval Vessel Search - Communist China

TO:

NPIC

1. Reference CLA requirement for photo search for "new generation" naval . vessels in operation or under construction in Communist China.

25X1A

2. Attached summarizes DIAAP-1's response to requirement No. C-C14-81,904.

Chief, DIAAP-1P

1 Enclosure 2 cys Increment #1 (2 pgs)

DIA review(s) completed.

HANDLE VIA

Approved For Release 2003/03/06": CIA-RDP81T00990R000100110001-0

25X1

25X1

BEST COPY Available THROUGHOUT FOLDER

- 3-		_
	Approved For Re 2003/03/06 : CIA-RDP81T00990R000100110001-0	5
1.	INCREMENT NO. 1	5
	The below listed shipyards were searched for new generation naval vessels afloat or under construction with the indicated results: 25X1A	
6	a. Dairen/Pt. Arthur Area Photos	
25X1A 25X1A 25X1A	(1) Dairen Main Yard - No unusual building activity observed. 1 "G" class SSB was observed on afloat alongside Pier No. 4. Several Shanshai class PTF and prob MK-6 class ICM were under construction on marine railways in this yard on the photography. Comparison with showed an unidentified vessel approximately 300' LOA, 30' beam, U/C or in repair, on marine railway #2.	4
25X1A	(2) <u>Luta Shipyard</u> - Analysis of photography produced negative results. No new generation naval vessels were observed.	
25X1A	(3) Pt. Arthur - Repair Yard/Submarine Base - The Pt. Arthur shipyard was covered on and a prob KOMAR class PTG was observed in drydock No. 2. A comparison was made with and the KOMAR PTG was not observed nor was there any other indication of "new generation" shipbuilding.	
23X IA 	b. Shanghai Complex - Photography 25X1A	
1-2 weins	(1) Kiangnan Yard - No unusual building activity observed. Yard engaged primarily in ship repair.	
·	(2) <u>Hutung Yard</u> - No "new generation" naval vessels were observed under construction or repair in this yard.	
	(3) Shanghai Shipyard (east) - Two 83' boats of the P-6 hull-type were observed in this yard (one on railway and one in water), however they did not appear to be unusually configured. No other unusual activity noted.	
	(4) Shanghai Shipbuilding and Repair Yard - Activity appears to consist of mership repair or building. No naval vessels observed.	
	(5) Shanghai Shipyard (west) - No naval vessels observed.	
	(6) Chunghua Yard - No naval vessels observed.	
	(7) <u>Kiousin (Chiuhsin) Yard</u> - Four U/I vessels observed on railways, length approximately 90 feet, possible merships.	-
	(8) <u>Tungchiatu Yard</u> - Repair and/or construction apparently limited to merships at time of photo coverage.	
	(9) Changhuapeng Yard - No naval vessels observed. Copy - Of Copies	
1		5.

Approved For Re 2003/03/06 : CIA-RDP81T00990R000100110001-0

1.1				Anna da Anna d Anna da Anna d	
(10)) Palianchang	Yard - Activity	at time of ph	otography limited	
o mership re	epair or consti	ruction.	-		
c. Cant	ton/Whampoa Are	ea:			25X1A
(1)	Tunglang Yard	l - No naval ves	sels nor new t	ypes under constru	etion
vas a PC type slightly simi null approxim mas its super cox-like stru caliber AA gu	naval ship. ilar to a Japar mately 180° L.(estructure slig acture aft of a	Moored at the onese PC of the Hall of the Hall of the Hall of the Hall of the Market of the Hall of th	FTshore wharf, syabusa class, ely 24° maximu amidships and ment consists	nusual vessel obsethis vessel appearant with a flush deck m beam. This unit a probable stack of probable small charge racks. No	red ed and
(3) ere noted.	Paihsienko Ya	<u>rd</u> - No naval ve	essels or new	types under constr	uction
					25X1A
(]+)	Nuishan Yard	- No new or unus	sual naval ves	sels observed.	
(5) ere noted.	Yukuo Yard -	No naval vessels	or new types	under constructio	n
hoto Referen	ces:				
5X1A					
				÷	·
					•
		4			
					•
			•		
•					
			,	CONTROL SYS	, EN OXER
				NOT THE PART OF TH	- >
				7 (

Approved For Release 2003/03/06 : CIA-RDP81T00990R000100110001-0

	Approved Formelease 2003/03/06 : CIA-RDP81T009 0001001/0
25X1A / / / / / / / / / / / / / / / / / / /	or Suggested memo to CGS
1.	The attached P. I. report titled "Increment No. 1" is a response to
	CIA in answer to CGS requirement No. C-Cl4-81,904.
2.	This comes as a complete surprise to us in view of the fact that we
	have been attempting to get in a posture to properly service all
1	headquarters requests. The latest survey having been conducted in
*	concert with CGS in August and September 1964.
, . 3.	We were not the only ones surpresed in as much as the CGS Liaison
25X1A	Officer at PID, was unaware of CGS levying CIA
	requirements directly on DIA.
	Had this requirement been received by PID it could have been handled
	departmentally or forwarded to the Ad Com - Secretariat for National
	consideration. However, such a CIA requirement levied directly on
	DIA was handled by DIA and not submitted to the NPIC secretariat or
	Ad. Com.
5.	We also understand that there are more requirements from CGS that
	have been levied directly on DIA. The CIA analys
	requesting the work was apparently unaware that CGS had farmed out
	his requirement to DIA.
25X1A 6.	
	C-Cl4-81,904 was as follows:
	(a) CGS believed that PID/IB backlog was such that a r
	relatively low priority project would not km receive
	attention for months.
25X1A	(b) talked with the Navy member of the NPIC
	and Com about doing the work - and it was agreed the Navy

Approved For Release 2003/03/06 : CIA-RDP81T00990R000100110001-0

GROUP 1.

27	Approved Forelease 2003/03/06: CIA-RDP81T009 000100110001-0 would accept the requirement.	
	(c) Later, the Navy Ad Com representative called Mr.	
25X1A	to state that since the Navy no longer carried	
	the responsibility to accept such work that the require-	
	ment should be submitted to DIA.	
25X1A	who ista	
!	stated DIA would be happy to do the work.	
	(e) The work was performed by DIA-API in	25X1A
	7. We do not feel that such maneuvering was necessary nor that it can	
	be justified. We feel relatively certain that it did not contribute	
	much to the image DIA may have of CIA.	
		25X1A